

---

## Restriction of Hazardous Substances (RoHS) Product Compliance Schedule

2SP-ISA	currently compliant
Parallel-PCI	currently compliant
Parallel-PCI 3.3V	currently compliant
Dual Parallel-PCI	currently compliant
Parallel-PCI/LP	currently compliant
Parallel Bi-directional	pending next build
ESL 1-DB9-232	currently compliant
ESL 1-RJ45-232	pending next build
ESL 1-DB9-422	currently compliant
ESL 2-DB9-232	currently compliant
ESL 2-RJ45-232	pending next build
ESL 4-DB9-232	currently compliant
ESL 4-DB9-232 CBL	currently compliant
ESL 4-RJ45-232	pending next build
ESL 5-DB9-232 EMB	pending next build
ESL 8-DB9-232 CBL	currently compliant
PayLink-IP/Dial	currently compliant
PayLink-IP/232	currently compliant
DataTap-IP	currently compliant

Product manufactured before July 2006 may or may not be RoHS compliant. Please order accordingly.